



**Peeper and Filtered Trident Samples (all $\mu\text{g/L}$)
River Mile 6.8 to 7.8**



**Peeper and Unfiltered Trident Samples (all $\mu\text{g/L}$)
River Mile 6.8 to 7.8**



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.


Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.

- Map Features**
- Docks and Structures
 - Navigation Channel
 - River Miles
 - GWPA Study Site
 - Upland ECSI Sites (2008)
 - Waterfront Taxlots


0 250 500 750 1,000 Feet

Map 5.5-1
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Total DDX ($\mu\text{g/L}$)
River Mile 6.8 to 7.8

**Peeper and Filtered Trident Samples (all $\mu\text{g/L}$)
River Mile 04 to 05**



**Peeper and Unfiltered Trident Samples (all $\mu\text{g/L}$)
River Mile 04 to 05**



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.


Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-2a

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Total PAHs ($\mu\text{g/L}$)
River Mile 04 to 05



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers
Docks & In-water Structures: digitized from October
2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:

T Mathematically derived value.

J The associated numerical value was approximated by the analytical laboratory.

U The analyte was not detected above the reported sample quantitation limit.



UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.

A Total value based on a limited number of analytes.


A = Total value based on a limited number of analyses.

Map 5.5-2b

**Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Total PAHs (μ g/L)
River Mile 05 to 06**



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos





Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.

- Map Features**
- Docks and Structures
 - Navigation Channel
 - River Miles
 - GWPA Study Site
 - Upland ECSI Sites (2008)
 - Waterfront Taxlots

0 250 500 750 1,000 Feet



Map 5.5-2c
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Total PAHs (µg/L)
River Mile 06 to 07

**Peeper, Unfiltered Trident, and Unfiltered Non-LWG Push Probe Samples (all $\mu\text{g/L}$)
River Mile 06 to 07**





Map 5.5-2d
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Total PAHs ($\mu\text{g/L}$)
River Mile 06 to 07, zoom


Peeper and Filtered Trident Samples (all µg/L)
River Mile 07 to 08



Peeper and Unfiltered Trident Samples (all µg/L)
River Mile 07 to 08



FEATURE SOURCES:
 Property and Taxlot Boundaries: Metro RLIS
 Channel & River miles: US Army Corps of Engineers.
 Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos




Qualifiers:
 T Mathematical derived value.
 J The associated numerical value was approximated by the analytical laboratory.
 U The analyte was not detected above the reported sample quantitation limit.
 UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
 A Total value based on a limited number of analytes.

- Map Features**
- Docks and Structures
 - Navigation Channel
 - River Miles
 - GWPA Study Site
 - Upland ECSI Sites (2008)
 - Waterfront Taxlots

0 250 500 750 1,000 Feet


Pepper and Filtered Trident Samples (all µg/L)
River Mile 04 to 05

X:\Projects\B0101\Portland_Harbor\SubTasks\Round3_TZW\Production_MXDs\TZW\Production_MXDs\TZW_Arsenic_Mile_4_to_5_20090401.mxd - 4/1/2009 @ 12:44:40 PM




Pepper and Unfiltered Trident Samples (all µg/L)
River Mile 04 to 05

X:\Projects\B0101\Portland_Harbor\SubTasks\Round3_TZW\Production_MXDs\TZW\Production_MXDs\TZW_Arsenic_Mile_4_to_5_20090401.mxd - 4/1/2009 @ 12:44:40 PM



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.



Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots


0 250 500 750 1,000 Feet

Map 5.5-3a

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Arsenic (µg/L)
River Mile 04 to 05



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.



Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots


0 250 500 750 1,000 Feet

Map 5.5-3b

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Arsenic (µg/L)
River Mile 05 to 06



FEATURE SOURCES:
 Property and Taxlot Boundaries: Metro RLIS
 Channel & River miles: US Army Corps of Engineers.
 Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
 PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.



Qualifiers:
 T Mathematically derived value.
 J The associated numerical value was approximated by the analytical laboratory.
 U The analyte was not detected above the reported sample quantitation limit.
 UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
 A Total value based on a limited number of analytes.

- Map Features:**
- River Miles
 - R2 GWPA Study Site
 - Docks and Structures
 - Navigation Channel
 - Waterfront Taxlots
 - Upland Sites ECSI (2008)

0 250 500 750 1,000 Feet

Map 5.5-3c

Portland Harbor RI/FS
 Remedial Investigation Report
 Transition Zone Water Chemistry
 Arsenic (µg/L)
 River Mile 06 to 07



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.

PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:

T Mathematically derived value.

J The associated numerical value was approximated by the analytical laboratory.

U The analyte was not detected above the reported sample quantitation limit.

UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.



A Total value based on a limited number of analytes.

Map Features


- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-3d
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Arsenic ($\mu\text{g/L}$)
River Mile 07 to 08



FEATURE SOURCES:
 Property and Taxlot Boundaries: Metro RLIS
 Channel & River miles: US Army Corps of Engineers.
 Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



Tabular Results Notes:
 T Mathematically derived value.
 J The associated numerical value was approximated by the analytical laboratory.
 U The analyte was not detected above the reported sample quantitation limit.
 UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
 A Total value based on a limited number of analytes.

Map Features


- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet


Map 5.5-3e

Portland Harbor RI/FS
 Remedial Investigation Report
 Transition Zone Water Chemistry
 Arsenic (µg/L)
 River Mile 08 to 09


**Pepper and Filtered Trident Samples (all $\mu\text{g/L}$)
River Mile 04 to 05**



**Pepper and Unfiltered Trident Samples (all $\mu\text{g/L}$)
River Mile 04 to 05**



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PS_T Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PS_p Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.


Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots


0 250 500 750 1,000 Feet

Map 5.5-4a

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Chromium ($\mu\text{g/L}$)
River Mile 04 to 05



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
 T Mathematically derived value.
 J The associated numerical value was approximated by the analytical laboratory.
 U The analyte was not detected above the reported sample quantitation limit.
 UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
 A Total value based on a limited number of analytes.



Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots


0 250 500 750 1,000 Feet

Map 5.5-4b

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Chromium ($\mu\text{g/L}$)
River Mile 05 to 06



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.


- Map Features:
- Docks and Structures
 - Navigation Channel
 - River Miles
 - GWPA Study Site
 - Upland ECSI Sites (2008)
 - Waterfront Taxlots

0 250 500 750 1,000 Feet


Map 5.5-4c

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Chromium (µg/L)
River Mile 06 to 07

**Peeper and Filtered Trident Samples (all $\mu\text{g/L}$)
River Mile 07 to 08**



**Peeper and Unfiltered Trident Samples (all $\mu\text{g/L}$)
River Mile 07 to 08**



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.


Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots


0 250 500 750 1,000 Feet

Map 5.5-4d
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Chromium ($\mu\text{g/L}$)
River Mile 07 to 08


Pepper and Filtered Trident Samples (all µg/L)
River Mile 08 to 09



Pepper and Unfiltered Trident Samples (all µg/L)
River Mile 08 to 09



FEATURE SOURCES:
 Property and Taxlot Boundaries: Metro RLIS
 Channel & River miles: US Army Corps of Engineers.
 Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



Tabular Results Notes:

- T Mathematically derived value.
- J The associated numerical value was approximated by the analytical laboratory.
- U The analyte was not detected above the reported sample quantitation limit.
- UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
- A Total value based on a limited number of analytes.

Map Features


- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-4e
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Chromium (µg/L)
River Mile 08 to 09


**Peeker and Filtered Trident Samples (all $\mu\text{g/L}$)
River Mile 04 to 05**

X:\Projects\B0101G_Portland_HarborSubTasks\Round3_TZWProduction_MXD\tzwm_Copper_Mile_4_to_5_20090819.mxd - 6/9/2009 @ 10:44:35 AM



**Peeker and Unfiltered Trident Samples (all $\mu\text{g/L}$)
River Mile 04 to 05**

X:\Projects\B0101G_Portland_HarborSubTasks\Round3_TZWProduction_MXD\tzwm_Copper_Mile_4_to_5_20090819.mxd - 6/9/2009 @ 10:44:35 AM



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:

- T Mathematically derived value.
- J The associated numerical value was approximated by the analytical laboratory.
- U The analyte was not detected above the reported sample quantitation limit.
- UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
- A Total value based on a limited number of analytes.

Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-5a

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Copper ($\mu\text{g/L}$)
River Mile 04 to 05



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.

Map Features


- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots



0 250 500 750 1,000 Feet

Map 5.5-5b

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Copper ($\mu\text{g/L}$)
River Mile 05 to 06

**Peeper, Filtered Trident, and Filtered Non-LWG Push Probe Samples (all µg/L)
River Mile 06 to 07**





FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.

PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:

T Mathematically derived value.

J The associated numerical value was approximated by the analytical laboratory.



U The analyte was not detected above the reported sample quantitation limit.

UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.


A Total value based on a limited number of analytes.

- Map Features**
- Docks and Structures
 - Navigation Channel
 - River Miles
 - GWPA Study Site
 - Upland ECSI Sites (2008)
 - Waterfront Taxlots

0 250 500 750 1,000 Feet



FEATURE SOURCES:
 Property and Taxlot Boundaries: Metro RLIS
 Channel & River miles: US Army Corps of Engineers.
 Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



Tabular Results Notes:

- T Mathematically derived value.
- J The associated numerical value was approximated by the analytical laboratory.
- U The analyte was not detected above the reported sample quantitation limit.
- UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
- A Total value based on a limited number of analytes.

Map Features

- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet




Map 5.5-5e

Portland Harbor RI/FS
 Remedial Investigation Report
 Transition Zone Water Chemistry
 Copper (µg/L)
 River Mile 08 to 09

Peeker and Filtered Trident Samples (all µg/L)
River Mile 04 to 05

X:\Projects\B0101_Portland_Harbor_SubTasks\Round3_TZW\Production_MXDs\TZW_Zinc_Mile_4_to_5_20090401.mxd - 4/1/2009 @ 1:29:28 PM




RM-4




Peeker and Unfiltered Trident Samples (all µg/L)
River Mile 04 to 05

X:\Projects\B0101_Portland_Harbor_SubTasks\Round3_TZW\Production_MXDs\TZW_Zinc_Mile_4_to_5_20090401.mxd - 4/1/2009 @ 1:29:28 PM

RM-4



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSP Indicates sample collected during the GWPA Pilot Study by small-volume peeper.



Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.

Map Features
Docks and Structures
Navigation Channel
River Miles
GWPA Study Site
Upland ECSI Sites (2008)
Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-6a

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Zinc (µg/L)
River Mile 04 to 05



FEATURE SOURCES:
 Property and Taxlot Boundaries: Metro RLIS
 Channel & River miles: US Army Corps of Engineers.
 Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



Map Features



- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet


PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:
 T Mathematically derived value.
 J The associated numerical value was approximated by the analytical laboratory.
 U The analyte was not detected above the reported sample quantitation limit.
 UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
 A Total value based on a limited number of analytes.

Map 5.5-6b
 Portland Harbor RI/FS
 Remedial Investigation Report
 Transition Zone Water Chemistry
 Zinc ($\mu\text{g/L}$)
 River Mile 05 to 06



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos



PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.

PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.

Qualifiers:



- T Mathematically derived value.
- J The associated numerical value was approximated by the analytical laboratory.
- U The analyte was not detected above the reported sample quantitation limit.
- UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
- A Total value based on a limited number of analytes.

Map Features


- Docks and Structures
- Navigation Channel
- River Miles
- GWPA Study Site
- Upland ECSI Sites (2008)
- Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-6c
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Zinc (µg/L)
River Mile 06 to 07



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos





PSt Indicates sample collected during the GWPA Pilot Study by Trident sampler.
PSp Indicates sample collected during the GWPA Pilot Study by small-volume peeper.
Qualifiers:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.


Map Features
Docks and Structures
Navigation Channel
River Miles
GWPA Study Site
Upland ECSI Sites (2008)
Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-6d
Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Zinc ($\mu\text{g/L}$)
River Mile 07 to 08



FEATURE SOURCES:
Property and Taxlot Boundaries: Metro RLIS
Channel & River miles: US Army Corps of Engineers.
Docks & In-water Structures: digitized from October 2001 0.33 ft. resolution color orthophotos




Tabular Results Notes:
T Mathematically derived value.
J The associated numerical value was approximated by the analytical laboratory.
U The analyte was not detected above the reported sample quantitation limit.
UJ The analyte was not detected above the reported sample quantitation limit; however, the reported quantitation limit was approximated by the analytical laboratory.
A Total value based on a limited number of analytes.

- Map Features**
- Docks and Structures
 - Navigation Channel
 - River Miles
 - GWPA Study Site
 - Upland ECSI Sites (2008)
 - Waterfront Taxlots

0 250 500 750 1,000 Feet

Map 5.5-6e

Portland Harbor RI/FS
Remedial Investigation Report
Transition Zone Water Chemistry
Zinc ($\mu\text{g/L}$)
River Mile 08 to 09



FEATURE SOURCES:
Transportation, Property, or Boundaries: Metro RLIS .
Channel & River miles: US Army Corps of Engineers.
Bathymetric Information: David Evans and Associates, Inc.

0 1,000 2,000 3,000 4,000 5,000 Feet

Map Features

- | | |
|------------------------|----------------------------|
| ■ Docks and Structures | ■ Upland ECSI Sites (2008) |
| ■ Bridges | ■ Waterfront Taxlots |
| — River Miles | ■ River Edge +13 ft NAVD |
| ■ Navigation Channel | |

Map 5.5-7

Portland Harbor RI/FS
Remedial Investigation Report
Groundwater Seep Sampling Locations